

Speeds and Feeds



- 1) Select your material in the ISO colored chart with respect to material description.
- 2) Start with a middle/average value for cutting speed, V_c (m/min) and feed per tooth, f_z (mm/tooth). Adjust the cutting speed and/or feed based on your cutting conditions.

Milling Series - HIEX/HPSM

Material			Recommended Cutting Values			
ISO	Material Description	Grade	V_c , SMM	F_z , MMPT (Face/Shoulder Milling)	F_z , MMPT (Grooving, Ramping, Helical Milling)	Depth of Cut, a_p
P	Steel	HU30	150 - 240	0.05 - 0.3	0.05 - 0.3	16.5 mm
		HP25	130 - 210	0.05 - 0.3	0.05 - 0.3	
		MKP30	250 - 350	0.05 - 0.3	0.05 - 0.3	
		HKP40	150 - 250	0.05 - 0.3	0.05 - 0.3	
M	Stainless Steel	HU30	90 - 150	0.05 - 0.25	0.05 - 0.15	
K	Cast Iron	HU30	120 - 200	0.08 - 0.35	0.08 - 0.2	
		MKP30	200 - 300	0.08 - 0.35	0.08 - 0.2	
		HKP40	150 - 250	0.08 - 0.35	0.08 - 0.2	
N	Aluminum & Non-Ferrous	HN30	500 - 1500	0.08 - 0.25	0.08 - 0.25	

NOTE: When surface and shoulder milling, the data refers to general cutting conditions and can be adjustable up to 350 SMM and 0.406 MMPT depending on user environment. In deep grooving, set the a_p under 5 mm and use coolant + air."



Speeds and Feeds



Feed Rate, Per Revolution (mm/min)
$v_f = f_n \cdot n$

Feed Rate, Per Tooth (mm/min)
$v_f = f_z \cdot n \cdot Z$

Feed Per Revolution (mm/rev)
$f_n = \frac{v_f}{n}$

Feed Per Tooth (mm)
$f_z = \frac{v_f}{n \cdot Z}$

Cutting Speed (m/min)
$v_c = \frac{\pi \cdot D_{tool} \cdot n}{1000}$

Spindle Speed (rev/min)
$n = \frac{v_c \cdot 1000}{\pi \cdot D_{tool}}$

Material Removal Rate (cm ³ /min)
$MMR = \frac{a_p \cdot a_e \cdot v_f}{1000}$

Metric

Symbol	Definition	Unit
v_f	Feed rate	<i>mm/min</i>
f_n	Feed per revolution	<i>mm/rev</i>
f_z	Feed per tooth	<i>mm</i>
v_c	Cutting speed	<i>m/min (SMM)</i>
n	Spindle speed	<i>rev/min (RPM)</i>
D_{tool}	Tool cutting diameter	<i>mm</i>
MMR	Material removal rate	<i>(cm³/min)</i>
a_e	Radial depth of cut	<i>mm</i>
a_p	Axial depth of cut	<i>mm</i>
Z	Number of teeth/flutes	