

Parameters, Diagnostics And Maintenance

Diagnostics | Maintenance | Parameters | Factory | Patches | Compensation | Activation

Search **F1**


<input type="checkbox"/>	Feature	Status	Date:
<input type="checkbox"/>	Machine	Feature Disabled	Remaining 12 Days 7 hrs
<input checked="" type="checkbox"/>	Macros	Purchased	Acquired 03-12-25
<input checked="" type="checkbox"/>	Rotation And Scaling	Purchased	Acquired 03-12-25
<input checked="" type="checkbox"/>	Rigid Tapping	Purchased	Acquired 03-12-25
<input checked="" type="checkbox"/>	TCPC and DWO	Purchased	Acquired 03-12-25
<input checked="" type="checkbox"/>	M19 Spindle Orient	Purchased	Acquired 03-12-25
<input checked="" type="checkbox"/>	High Speed Machining	Purchased	Acquired 03-12-25
<input checked="" type="checkbox"/>	VPS Editing	Purchased	Acquired 03-12-25
<input checked="" type="checkbox"/>	Media Display	Purchased	Acquired 03-12-25
<input checked="" type="checkbox"/>	Fourth Axis	Purchased	Acquired 03-12-25
<input checked="" type="checkbox"/>	Fifth Axis	Purchased	Acquired 03-12-25
<input type="checkbox"/>	Custom Rotaries	Feature Disabled	Purchase Required
<input checked="" type="checkbox"/>	Max Memory: 1GB	Purchased	Acquired 03-12-25
<input checked="" type="checkbox"/>	Wireless Networking	Purchased	Acquired 03-12-25
<input checked="" type="checkbox"/>	Compensation Tables	Purchased	Acquired 03-12-25
<input checked="" type="checkbox"/>	Through Spindle Coolant	Purchased	Acquired 03-12-25
<input checked="" type="checkbox"/>	Max Spindle Speed: 15000 R...	Purchased	Acquired 03-12-25
<input type="checkbox"/>	Robot	Feature Disabled	Purchase Required

*Tryout time is only updated while Feature is enabled.

ENTER Turn On/Off Feature

Program G59 G43 H1

Axis	(IN)	Load
X	-23.7890	6%
Y	-3.4820	5%
Z	0.0000	53%
B	-0.003	0%
C	0.001	0%

 Low Coolant

Timers And Counters

This Cycle:	23:44:40
Last Cycle:	23:44:40
Remaining	0:00:00
M30 Counter #1:	0
M30 Counter #2:	0
Loops Remaining:	0









