
Haas Workholding by Mitee-Bite Products







Pitbull[®] Clamp Instructions

- 1. Mill a slot for the Pitbull® Clamp using "B" and "C".
- 2. Drill and tap from edge of workpiece "A".
- 3. Assemble clamp with o-ring below clamp body.
- 4. Position clamp as shown in diagram and loosely screw to fixture.
- 5. Insert workpiece and tighten cap screw.