



Air & Power



For precise locations and specifications please use template in Anchoring Kit found at Haascnc.com




[Maintain 3 feet [915mm] clearance to the nearest obstruction around all sides of machine perimeter for maintenance access]


Note:

Machine must be placed on one continous concrete slab. Slab should extend 12in [305mm] beyond anchor holes in all directions


Anchor Pattern


Anchor Hole Detail \emptyset 0.625in[25mm] $\overline{\lor}$ 2.0in[50mm]- $\overline{\lor}$ 2.25in[57mm]







Depth Breakdown









*Due to vendor variations discretion should be taken to verify validity of provided dimensions

SPINDLE FACE TO UNION

ADAPTOR

32.7

J

830.58